CER FIED CORNER RECORDATION
Corner <u>C-N-S 1/64 S24</u> T. <u>33</u> N., R. <u>34</u> W., P.M.M. <u>Lincoln</u> County
Record :
1970 Section Subdivision by Ninneman Engineering (Book 1 Page 209 Certified Corner Recordation, Lincoln County Records). No monumentation.
Found Evidence :
None
Perpetuation:
The position for the C-N-S 1/64 cor. for Sec. 24 was determined from a closed traverse survey of the SE 1/4 of Sec. 24 by Davis Surveying, Inc. during February of 1999. At the computed position, set a 5/8 inch diam. steel rebar 24 ins. long, 22 ins. in the ground, with a 3 1/4 inch diam. alum. cap marked as shown below, from which:
A Douglas Fir 15 ins. diam. bears N. 26° W., 33.50 ft. dist., scribed (C-N-S 1/64
S24 BT). A Douglas Fir 9 ½ ins. diam. bears N. 46° E., 30.50 ft. dist., scribed (C-N-S 1/64 S24 BT).
Painted 6 inch wide bands and scribed faces red.
Attached Bearing Tree and Land Survey Monument signs to both trees.
Set a 6 ft. long steel post with Land Survey Monument and Property Line decals 3 ft.
N. of set monument on line.
C-N-5/64 524 525-5 199
Magnetic Declination: 18° E.
CERTIFICATION I, John Damon certiff the Information shown herein is true and correct Signature of Ground Party Chief I, Nen: E: Davis certify that this Corner, Record Correctly represents work performed the original of the corner recording to the corner record of the corner re
Section
Office of Clerk and Recorder, County of AMCA This "corner record" was filed for record on May 24, 1993 was noted on the cross-index plat and is assigned page No
Cross Index No. <u>C-N-S 1/64 S24</u> T. <u>33</u> N., R. <u>34</u> W., PMM ● THIS CORNER