INSTRUCTIONS

- 1. Original and/or subsequent record used to evaluate the corner position
- 2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated corners.
- 3. Description of monument and accessories set to perpetuate the corner position.
- 4. Sketch of corner, show all pertment data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, ea
- 5. Certification must be signed and sealed by Land Surveyor registered in the State of Montana.
- 6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

Corner E 1/16 SEC. 16 T. 33N R. 34W P.M.M. Lincoln County

The new corner monument was established as a result of a subdivisional survey of the Section. Said subdivisional survey was made in accordance with methods and procedures contained in the <u>Manual of Surveying Instructions</u> (1973); U.S. Bureau of Land Management.

FOUND:

Found rebar and cap marked "JHN 4661S" (disturbed)

A 14" tamarack bears S2834°E, 38.4 feet, no visible scribing, healed scar and snow blaze, no tag found.


ESTABLISHED:

Set a 31/4" aluminum cap on a 5/8" rebar, set flush with ground, marked as shown below; from which:

A 12" Hemlock bears N14%°E, 68.8 feet, scribed E1/16 S9 BT.

Set a 6' metal post, with land survey monument decal attached, 2.0 feet east and 2.0 feet south of monument.





| Office of Clerk and Records | P |
|---|----------------|
| 204578 BOOK: CCR CCGR'S PAGE: 11070 Pages: 1 | } ! ! ! |
| record" was filed for STATE OF MONTANA LINCOLN COUNTY | |
| RECORDED: 07/25/2007 10:15 KOI: CCER'S | 116 |
| was noted on the crot tammy D. Lauer Clerk and recorder | 140 |
| was noted on the cro: TAMMY D. LAUER CLERK AND RECORDER book no | |
| TO: FILED , | |
| County Official | † } |

Cross Index No. J12 T. 33N R. 34W PMM

Adopted July 1, 1981, Montana Board of Professional Engineers & Land Surveyors

• - Corner this sheet