INSTRUCTIONS

- 1. Original and/or subsequent record used to evaluate the corner position.
- 2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated corners.
- 3. Description of monument and accessories set to perpetuate the corner position.
- 4. Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.
- 5. Certification must be signed and sealed by Land Surveyor registered in the State of Montana.
- 6. Fill in Cross Index & Section Diagram at bottom of sheet

CERTIFIED CORNER RECORDATION

	Corner _	C-E-SW 1/64 SEC. 16	T	33N_	R.	34W	P.M.M.	Lincoln	Count
--	----------	---------------------	---	------	----	-----	--------	---------	-------

The new corner monument was established as a result of a subdivisional survey of the Section. Said subdivisional survey was made in accordance with methods and procedures contained in the Manual of Surveying Instructions (1973); U.S. Bureau of Land Management.

FOUND:

A 5/8" rebar within positional tolerance.

ESTABLISHED:


Replaced plastic cap with a 31/4" aluminum cap on found rebar, set flush with ground, marked as shown below; from which:

An 11" Fir bears N24%°E, 27.5 feet, scribed CE SW1/64 S16 BT.

An 11" Fir bears S50%°E, 21.0 feet, scribed CE SW1/64 S16 BT.

Set a 6' metal post, with land survey monument decal attached, 2.0 feet north and 2.0 feet west of monument.





				4
Office of Clerk and Re	204582 BOOK	: CCR CC&R'S	PAGE: 11074	Pages: 1
record" was filed for 1				_
	RECORDED: 07/25,	/2007 10:35 KOI:	CC&R1S	
was noted on the cros	TAMMY D. LAUER	CLERK AND RECORD	ER / 1/	, 7
was noted on the cros book no.	FEE: \$0.00 TO: FILED ,	BY	lomdall, a	depuly_

County Official

Cross Index No. NN13 T. 33N R. 34W PMM

• - Corner this sheet

16