## INSTRUCTIONS

- 2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated
- 3. Description of monument and accessories set to perpetuate the corner position.
- 4. Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.
- 5. Certification must be signed and sealed by Land Surveyor registered in the State of Montana.

  6. Fill in Cross Index & Section Diagram at bottom of sheet.

## CERTIFIED CORNER RECORDATION

33 N., R. 34 W., P.M.M. 1/1024 Secs. 20 & 21 Lincoln Corner ... County No records found. No evidence found on the ground. III. At the position determined by survey, set an aluminum rod, 3/4 ins. diam., 30 ins. long, 29 ins. in the ground, with 3 1/4 ins. diam., U.S.D.A. Forest Service aluminum cap, marked as shown:

1/1024 х 7322LS 1992


Established two new bearing trees:

A fir, 9 ins. diam., bears  $844^{\circ}E$ , 19.2 ft. dist., mkd. 1/1024 S21 BT. A fir, 9 ins. diam., bears  $829^{\circ}W$ , 15.8 ft. dist., mkd. 1/1024 S20 BT.

Painted red bands around the bearing trees and attached Land Survey Monument and Bearing Tree signs.

Set a 6 ft. galvanized steel guard post with Land Survey Marker and Property Boundary decals, North, 3 ft.

Magnetic Declination: 20 East



## SKETCH OF CORNER

CERTIFICATION

Thomas M. Hommel

Alvah P. Hughes

certify that this Corner Record correctly represents by me or under my direction in co Recordation Act." (70-22-101, et seq., )

with 12/28/92 \_\_\_\_Reg. No. 732213

Sec.

\_\_\_\_T. \_\_\_\_33\_N\_\_R. \_\_\_\_31/\_w'

Employer: U.S. FOREST SERVICE

\_ . This "corner Office of Clerk and Recorder, County of record" was filed for record on \_ was noted on the cross-index plat and is assigned page No. County Official book No. .

Cross Index No. -

.125Q-9

· - corner this sheet