
## **CERTIFIED CORNER RECORDATION**

Corner CE 1/16 Sec. 26 T. 33N R. 34W P.M., MT Lincoln County

- I. No History Found.
- II. No Evidence Found.
- III. Set by survey, a 3/4 in. diam. x 30 ins. long aluminum rod, with a 3 1/4 in. diam. aluminum cap, set flush with the ground, mkd. as shown:




Established two bearing trees and one post:

A larch, 14 ins. diam., bears N12°W, 5.1 ft. dist., mkd. "CE 1/16 S26 BT". A larch, 16 ins. diam., bears N52°W, 25.0 ft. dist., mkd. "CE 1/16 S26 BT". A 6 ft. steel guard post, North, on property line, 3.0 ft. distance from the corner.

Painted bearing trees and attached Land Survey Monument and Bearing Tree signs. Attached Land Survey Monument and Property Boundary decals to the post.

Magnetic Declination: 20° East.



CERTIFICATION OF THE STATE OF T
I Steve Boyer
certify the information shown harein is an Aland costoc:
\$ 1/2. (8TET) (O)
- CORV
ı, Ronald A. Pearson
certify that this Corner Record correctly represents work performed by me or under my
direction in compliance with the "Somer Recordation Aut" (70-22-101, et seq., M.C.A.)
1 2 est 12, 4 co
Signature of Surveyor & Seal
Date: 06/19/97
Date. 00/10/07
Reg. No.: 9008LS
Employer: U.S. FOREST SERVICE

Sec. 26

Cross Index No

T-20

33N

P.M., MT