
CERTIFIED CORNER RECORDATION

Corner S 1/16 Sec. 25&26 T. 33N R. 34W P.M., MT Lincoln County

- I. No History Found.
- II. No Evidence Found.
- III. Set by survey, a 3/4 in. diam. x 30 ins. long aluminum rod, with a 3 1/4 in. diam. aluminum cap, set flush with the ground, mkd. as shown:



Established two bearing trees and two posts:

A larch, 10 ins. diam., bears S22°E, 14.9 ft. dist., mkd. "S 1/16 S25 BT".


A balsam fir, 9 ins. diam., bears S28°W, 15.8 ft. dist., mkd. "S 1/16 S26 BT".

A 6 ft. steel guard post, West, on property line, 3.0 ft. distance from the corner.

A 6 ft. steel guard post, South, on property line, 3.0 ft. distance from the corner.

Painted bearing trees and attached Land Survey Monument and Bearing Tree signs. Attached Land Survey Monument and Property Boundary decals to the posts.

Magnetic Declination: 20° East.




I. Ronald A. Pearson
certify that this Corner Record correctly, represents work performed by me or under my direction in compliance with five "Corner Recordation Act" (70-22-101, et seq., M.C.A.)

Signature of Surveyor & Seal
Date: Q6/24/97

Reg. No.: 9008LS

Employer: U.S. FOREST SERVICE



Cross Index No

U-21

33N

4Ŵ

- corner this sheet