
## **CERTIFIED CORNER RECORDATION**

Corner CS 1/16 Sec. 26 T. 33N R. 34W P.M., MT Lincoln County

- I. No History Found.
- II. No Evidence Found.
- III. Set by survey, a 3/4 in. diam. x 30 ins. long aluminum rod, with a 3 1/4 in. diam. aluminum cap, set flush with the ground, mkd. as shown:



Established two bearing trees and two posts:

A fir, 14 ins. diam., bears S04°E, 39.5 ft. dist., mkd. "CS 1/16 S26 BT".


A fir, 14 ins. diam., bears S58°W, 31.5 ft. dist., mkd. "CS 1/16 S26 BT".

A 6 ft. steel guard post, West, on property line, 3.0 ft. distance from the corner.

A 6 ft. steel guard post, North, on property line, 3.0 ft. distance from the corner.

Painted bearing trees and attached Land Survey Monument and Bearing Tree signs. Attached Land Survey Monument and Property Boundary decals to the posts.

Magnetic Declination: 20° East.



I. Ronald A. Pearson
certify that this Corner Record correctly represents work performed by me or under my direction in compliance with the "Corner Recordation Act" (79-22-101, et seq., M.C.A.)

Signature of Surveyor & Seal

Date: 06/24/97

Reg. No.: 9008LS

Employer: U.S. FOREST SERVICE

Office of Clerk and Recorder, County of _	LINCOLN . This "corner record" was filed for record
on JULY 31 1997was noted	on the cross-index plat and is assigned page No. $9857$
in book No	CORAL M.CUMMINGS By DUB

Sec. 26

• corne