## CERTIFIED CORNER RECORDATION

Corner S S 1/64th Cor Sec 8 T. 34N R. 25W P.M.M. Lincoln County

- 1. NONE
- 2. Found:

A Rebar, 5/8 ins. diam. with Yellow plastic cap mkd. #7328S

Replaced Yellow plastic cap with an Aluminum Cap, 31/4 ins. diam., 0.1 ft. above ground, mkd. as shown; Established:

A Douglas Fir, 19 ins. in diam., bears N8E, 82.6 ft. dist., scribed "S—S 1/64 S8 BT"; A Douglas Fir, 8 ins. in diam., bears N52E, 67.0 ft. dist., scribed "S—S 1/64 S8 BT"; Steel posts with LSM decal bear North, 2.0 ft. dist. and East, 2.0 ft. dist.



## MAGNETIC DECLINATION - 15"2' EAST

19" D Fir N8E, 82.6'

8" Fir N52'E, 67.0'

Steel Post North and East, 2.0' Erich 9748 LS

## SKETCH OF CORNER

Office of Clerk and Recorder Caustinate. Lincoln 230076 BOOK: CCR CCER'S

This "comer PAGE: 11675 Pages: 1

record was filed for rec: STATE OF MONTANA LINCOLN COUNTY RECORDED: 12/09/2010 10:35 KOI: CCER'S

Was noted on the cross- TAMMY D. LAUER CLERK AND RECORDER

book No. .


FEE: \$0.00

P.O. BOX 1863, SANDPOINT, ID. 83860, ВУ TO: GLAHE & ASSOC., INC.

H-5

J-5 t 34N R 25W PMM

Cross Index No.\_ Adopted July 1, 1981, Montana Board of Professional Engineers & Land Surveyors



corner this sheet

·