## CERTIFIED CORNER RECORDATION

Corner SE-SW 1/64th Cor Sec 7 T. 34N R. 25W P.M.M. Lincoln County

- 1. NONE
- 2. Found:

A 5/8 ins. rebar with yellow plastic cap mkd. #7328S

3. Set:


Replaced yellow plastic cap with an Aluminum Cap, 3¼ ins. diam., on the 5/8 ins. Rebar, flush with ground, mkd. as shown;

Established:

A Douglas Fir, 11 ins. in diam., bears N12'E, 18.0 ft. dist., scribed "SE-SW 1/64 S7 BT"; A Douglas Fir, 12 ins. in diam., bears S88'E, 8.1 ft. dist., scribed "SE-SW 1/64 S7 BT"; Steel posts with decals bear North and East, 2.0 ft. dist.



MAGNETIC DECLINATION - 15°2' EAST



.

•

والمحاربة والمحاربة والمحاربة والمسترانية كالمحاليين والمحاربة والمحاربة and the second of the second o