CERTIFIED CORNER RECORDATION

Corner SE-SE 1/64th Cor Sec 7 T. 34N R. 25W P.M.M. Lincoln County

- 1. NONE
- 2. Found:

A 5/8 ins. rebar with yellow plastic cap mkd. #7328S

3. Set:

Replaced yellow plastic cap with an Aluminum Cap, 3½ ins. diam., on the 5/8 ins. Rebar, mkd. as shown; Established:

A Ponderosa Pine, 24 ins. in diam., bears N50°E, 55.5 ft. dist., scribed "SE—SE 1/64 S7 BT"; A Douglas Fir, 17 ins. in diam., bears N75°E, 54.1 ft. dist., scribed "SE—SE 1/64 S7 BT"; Steel posts with decals bear South and West, 2.0 ft. dist.



corner this sheet

MAGNETIC DECLINATION - 15°2' EAST CERTIFICATION 24" P Pine Erich Shrad N50'E, 55.5' 17" D Fir N75°E, 54.1' Steel Posts South and West, 2.0 Swamp 30' dist 9748 LS SKETCH OF CORNER Office of Clerk and Recorder, Caustinate Lincoln Courts .. This "corner PAGE: 11684 Pages: 1 Sec. record" was filed for record STATE OF MONTANA LINCOLN COUNTY RECORDED: 12/09/2010 10:44 KOI: CCER'S was noted on the cross-inde TAMMY D. LAUER CLERK AND RECORDER FEE: \$0.00 BY: Sunne Sunne To: GLAHE & ASSOC., IEC. P.O. BOX 1863, SANDPOINT, ID. book No. H-4 <u>т. 34N</u> r. <u>25W</u> рмм Cross Index No._ Adopted July 1, 1981, Montana Board of Professional Engineers & Land Surveyors

•

•

7 · • · · · · · ·