## CERTIFIED LAND CORNER RECORDATION


(REFERENCE FSM 7153.53)

DESCRIPTION OF CORNER EVIDENCE FOUND, AND ORIGINAL RECORD (IF KNOWN)

Iron pipe with B.L.M. brass cap, marked as shown from which A 12" Douglas Fir, Sho°E, 50.7 Ft. A 10" Douglas Fir, Nh0°W, 2h.3 Ft.

1960 BLM Record: A 7" Fir, bears N40°45'W, 36 3/4 lks, mkd 1/4 S24 BT A 7" Fir, bears S42°59'E, 77 lks., mkd. 1/4 S19 BT

Raise a mound of stone 3 Ft. base 2 Ft. high W. of



DESCRIPTION OF MONUMENT AND ACCESSORIES ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

Date of work: 19.79......

Corner in good condition as found

SKETCH, WITH COURSE AND DISTANCE TO ADJACENT CORNERS IF DETERMINED IN THIS SURVEY. (MAY SKETCH OR PASTE REPRODUCTION ON REVERSE SIDE.)

See Certificate of Survey No. 749

Surveyor's Seal



certify that the information shown herein is true and correct.

Signature of Ground Party Chief

Thomas C. Hill certify that I have carefully performed or reviewed the work done on the diagrammed corner as reported on this recordation form and approve the same.

Signature of Surveyor

DIAGRAM OF CORNER:

T34N **R26W** R25W S24 **S1**9

= Corner recorded on the sheet

5612**-**5 Registration Number

Office of Clerk and Recorder, County of Lincoln

This "corner record" was filed for record on the 3rd day of March

noted on the cross-index plat and is

assigned page No. 665, in book No.

• • ţ, ..... . . Ø 12... •