
CERTIFIED CORNER RECORDATION

Corner	N-S 1/64	Sec.	17	T	34N_	R.	25 W	P.M., M	T Lincoln	County

- I. No previous history found.
- II. Found a 1/2 in. diam. rebar with a yellow plastic cap, mkd. 7318S.
- III. At the corner position as determined by survey, set a 30 in. long, 3/4 in. diam., alum. pipe, 27 ins. in the ground, with a 3 1/4 in. diam. alum. cap, mkd. as shown:



Established two bearing trees:


A fir, 8 ins. diam., bears S51°E, 30.3 ft. dist., scribed "N-S 1/64 S16 BT". A fir, 25 ins. diam., bears S15°W, 58.1 ft. dist., scribed "N-S 1/64 S17 BT".

A rebar, 1/2 in. diam., with a yellow plastic cap, mkd. 7318S, South, 13.3 ft. dist. from monument.

Painted bearing trees and attached Land Survey Monument and Bearing Tree signs.

Set a 6 ft. steel guard post, West, 3.0 ft., with Land Survey Monument and Property Boundary decals.

Magnetic Declination: 20° East.



.