
CERTIFIED CORNER RECORDATION

Corner C-S-N-S 1/256 Sec. 20 T. 34N R. 25W P.M., MT Lincoln County

- I. No previous history.
- II. No evidence found.
- III. At the position determined by survey, set a 21 ins. (rod was driven into a root and 9 ins. were sawn off) long, 3/4 in. diam. alum. rod, 17 ins. in the ground, with a 3 1/4 ins. diam. alum. cap mkd.:




from which:

A double-top larch, 14 ins. diam., bears S41°E, 41.1 ft. dist., mkd. "X BT". A larch, 11 ins. diam., bears S4°W, 54.8 ft. dist., mkd. "C-S-N-S 1/256 S20 BT".

Painted bearing trees and attached Land Survey Monument and Bearing Tree signs. Set a steel guard post West, 3.0 ft. dist. from corner, with Land Survey Monument and Property Boundary decals.

Magnetic Declination: 20° East.



Sec. 20

oss Index No. P.75-07 T. 34N R. 25W P.M., W

Marine Commence of the Commenc