
- CERTIFIED CORNER RECORDATION -

Corner NE 1/16 Sec. 23 T. 34N R. 26W P.M., MT Lincoln County

I. <u>1979 Certified Corner Recordation by Thomas C. Hill, 5612-S</u>: Set by survey, a 3 in. diam., 30 ins. long, aluminum pipe, 24 ins. in the ground, cap mkd. as shown, with a collar of stone.



Established two bearing trees:

A larch, 8 ins. diam., bears N38°40'E, 20.0 ft. dist., mkd. "X" "BT". A pine, 6 ins. diam., bears S42°04'W, 17.0 ft. dist., mkd. "NE 1/16 S23 BT".

II. Found a 3 in. diam., 30 ins. long aluminum pipe, protruding 6 ins. above the ground, mkd. as shown, with a collar of stone.

from which:


A larch, 8 ins. diam., bears N38°E, 20.0 ft. dist., mkd. "X" "BT". A pine stump and log, 6 ins. diam., bears S42°E, 17.0 ft. dist., mkd. "NE 1/16 S23 BT".

III. Established one new bearing tree:

A larch, 10 ins. diam., bears S05°W, 7.7 ft. dist., mkd. "NE 1/16 S23 BT".

Painted bearing trees and attached Land Survey Monument and Bearing Tree signs.

Magnetic Declination: 20° East



Cross Index No.

O-20

T. 34N

R. '

м.. мт