
- CERTIFIED CORNER RECORDATION -

Lincoln P.M., MT County Corner 1/4 22 & 23 Т, 34N R. 26W

- 1894 G.L.O. Record by Frank L. Sizer et. al.: Set a post, 3 ft. long, 3 ins. square, 24 ins. in the ground, I. for 1/4 sec. cor. mkd. "1/4 S" on W. Face. Established two bearing trees.
 - 1960 B.L.M. Remonumentation by David R. Cünningham et. al.: The 1/4 sec. cor. of secs. 22 and 23, as determined from the remains of the original bearing trees. At the corner point, set an iron post, 30 ins. long, 2 1/2 ins. diam., 26 ins. in the ground, in concrete, with brass cap mkd. as shown.



Established two new bearing trees and raise a mound of stone, 3 ft. base, 2 ft. high, W. of the iron post.

1979 Certified Corner Recordation, Certificate of Survey No. 750, by Thomas C. Hill, 5612S: Found iron pipe with B.L.M. brass cap, mkd. as shown.

from which:

- A 12" Fir, bears N59°31'W, 90 lks., healed face.
- A 10" Fir, bears S29°33'E, 84 lks., healed face.
- Found a 2 1/2 in. diam. pipe, firmly set, protruding 3 ins. above ground, with a 3 1/4 in. diam. brass cap II. mkd. as shown.

from which:

- A fir, 15 ins. diam., bears S30°E, 56.1 ft. dist., with a healed face. (BLM-record) A fir, 14 ins. diam., bears N60°W, 59.4 ft. dist., with a healed face. (BLM-record)
- Painted bearing trees and attached Land Survey Monument and Bearing Tree signs. III.

Magnetic Declination: 20° East

