CERTIFIED CORNER RECORDATION SW1/16 Sec. 14 T. 34 N. R. 26 W. P.M.M. LINCOLN County

- Record: No previous record.
- II. No evidence found.
- At the position determined by survey, set a 3/4 in. diam. aluminum rod, 48 ins. long, 43 III. ins. in the ground, with a 3 1/4 in. diam. aluminum cap marked as shown. Build a collar of stone 1 ft. diam. to bottom of cap.

T34N R26W SW 1/16 **S14** 13769LS 2000

The new bearing trees:

A larch, 14 ins. diam., N70°W, 33.5 ft., marked SW 1/16 S14 BT. A larch, 14 ins. diam., N4°W , 56.2 ft., marked "X" BT.

A location poster on a fir, 22 ins. diam., S20°W, 29.9 ft.

Set a 6 ft. galvanized steel guard post 3.0 ft. south and east, with Property Boundary and Land Survey Monument decals attached. Attached Bearing Tree and Land Survey Monument signs to the bearing trees. Attached brass disc directly above scribed "B" on both bearing trees. Disc reads LS 13769. Painted red bands around the bearing trees. The corner falls SE, approximately 15 ft. of a road.


Date of Fieldwork: 7/13/2000 Survey crew: Marc Burkhart

Magnetic declination: 18° East assumed

Equipment used: Hand compass and loggers tape

U.S. Forest Service, Supervisiors Office, 1101 Hwy. 2 West, Libby, MT 5992

Date: 4/02/2003 Reg. No. 13769LS Employer: U. S. Forest Service




Lincoln ____ This "corner Office of Clerk and Recorder, County of _ 7-10-03 record" was filed for record on _ was noted on the cross—index plat and is assigned page No. ... To Dennie. County Official

Sh+ 20/2

Cross Index No. M-18 T. 34N. R. 26W. P.M., MT

Adopted July 1, 1981, Montana Board of Professional Engineers & Land Surveyors



· corner this sheet

TO THE TOTAL PROPERTY OF THE PARTY OF THE PA

7-10-03

En Meneral

16877