- 4. Sketch or corner, show all pertinent data which can best be shown in a sketch example, co topography ties, position of accessories, etc.
- Certification must be signed and sealed by Registered Land Surveyor in State of Monta.
   Fill in Cross Index & Section Diagram at bottom of sheet.

### CERTIFIED CORNER RECORDATION

T. 34N R. <u>26</u>W 29,30,31 LINCOLN Corner <u>Sec.</u>

# RECORD: GLO 1895

Set a post 4' long, 4" sq., 24" in the ground, for Cor. to Secs. 29, 30, 31, & 32 marked T34N S 29 on NE; R26W S 32 on SE; S31 on SW and S 30 on NWfaces, with 1 notch on S and 5 notches on E edges; from which A fir 10" diam. bears N74½ E, 17 lks. dist. mkd. T34N R26W S29 BT.

A spruce 8" diam. bears S45½ E, 10 lks. dist. marked T34N R26W S32 BT.

A tamarack 10" diam. bears S15½ W, 30 lks. dist. marked T34N R26W S31 BT.

A spruce 8" diam. bears N53 W, 12 lks. dist. marked T34N R26W S30 BT.

## RECORD: BLM 1960

The cor. of secs. 29, 30, 31, and 32 monumented with a disintegrated wooden post, firmly set in the ground, and witnessed by the remains of three of the original bearing trees. At the corner point set an iron post 30" long, 2%" diam., 26" in the ground, in concrete, with brass cap from

which the remains of the original bearing trees:

A dead fir, 10" diam., bears N73°E, 17 lks. dist., mkd. T34N R26W S29

BT. (Record: N74½°E, 17 lks.)

A stump 12" diam., bears S37½°E, 10 lks. dist. (Record: S45½°E 10 l)

A dead larch 12" diam., bears S20½°W, 30 lks. dist., mkd. with an overgrown blaze. (Record: S15½°W, 30 lks) (Record: S45<sup>1</sup> E 10 1ks)

The new bearing trees:

A larch 12" diam., bears N41 3/4°E, 34 lks. dist., mkd. T34N R26W S29 BT.

A larch 10" diam. bears S3°E, 20 lks. dist., mkd. T34N R26W S32 BT.

A larch 11" diam. bears S31 3/4°W, 49 lks. dist., mkd T34N R26W S31 BT.

A cedar 8" diam., bears N73°W, 64 lks. dist., mkd. T34N R26W S30 BT.

#### FOUND:

3½" BLM Brass Cap on a Steel Pipe.
N43°E 21.8' 14" tamarack scribing overgrown.
\$02°E 13.4' 14" tamarack scribing overgrown.
\$31°W 32.8' 13" tamarack scribing overgrown.
N74°W 41.8' 15" cedar scribing overgrown.
Original 10" down fir N73°E 17 1ks (11.22')

#### MAINTENANCE:

Set a 6' Steel Post 3' away from corner. Maintained bearing trees with sign's and paint.

ANT A
CERTIFICATION  I. Glenn M. Knoole H. GENE  Certify the information shows herein is true and correct. WARREN  2734 S  Signature Ground Party Chiefe  I. H. Gene Warren Surry  certify that this Corner Record correctly represents work photographillit by me or under by direction in compliance with the "Corner Recordation Act" (70-22-10), et seq., M.D.A.)  Signature of Surveyor & Seal  Date: 7-1-88 Reg. No. 2734S  Employer: Rocky Mountain Surveyors
Sec. 31
day of 19 88  75  in  ly See See See See See See See See See Se

V-5 T. 34N R. 26W PMM

corner this sheet

γ. t, The state of the s -164