INSTITUCTIONS

1. Original and/or subversel record used to evaluate the corner position.
2. Description of evidence round, note discrepancies in the record, state method of extability. ng lost or obliterated

3. Description of monument and accessories set to perpetuate the corner position.

4. Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.

5. Certification must be signed and sealed by Registered Land Surveyor in State of Muntans.

6. Fill in Cross Index & Section Diagram at bottom of sheet.

## **CERTIFIED CORNER RECORDATION**

CW1/16 S27 T. 34N R. 26W P.M.M. Lincoln

Record of Original Corner No previous record on file.

Description of Corner Evidence Found No evidence found on ground.

## Description of Monument and Accessories Set

Set a standard 3 1/4" dia. Forest Service aluminum cap on a 3/4" x 30" aluminum shaft 19" in the ground (hit a rock outcrop) with a 3' x 3' rock cairn from which:

A 7 1/2" larch bears  $S65^{\circ}W$ , 33.1 ft. dis. scribed CW1/16S27BT

A 10 1/2" douglas fir bears N23°W, 18.6 ft. dis. scribed CW1/16S27BT

Bearing trees were signed and blazes painted red. Placed a 6 ft. steel post with Land Survey Monument decal attached 6 ft. west of corner. Corner falls on east slope in thick timber.



	9958 LS 9958 LS 9958 LS
SKETCH OF CORNER	CERTIFICATION  1. Steven R. Mover cerilly the information shown herein is true and correct.  Signature Ground Party Chief  James R. Staples  cerilly that this Corner Hereul decorrectly represents work profosmind by me or under by direction in compilance with the "Curner Recordation Act" (7021-101, et seq., M.D.A.).  Signature bl-Súrveyor & Seal  Date: 10/5/90 Reg. No. 9958LS  Employer: J.R.S. & Associates
Office of Clerk and Recorder, County of Lincoln record" was filed for record on the	Sec. 27  This "corner day of 1990  323 In Such Bucket  Sala PMM  Corner this sheet

SELVAL STAPLES SUBSTITUTE OF S

The second of th