DESCRIPTION OF CORNER EVIDENCE FOUND, AND ORIGINAL RECORD (IF KNOWN)

NONE

## DESCRIPTION OF MONUMENT AND ACCESSORIES ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

Date of work: 1979

Set a 3" X 30" Aluminum pipe, 24" in ground with a collar of stone

Pipe marked as shown:

from which: A 9" fir, N55°16'E, 37.8 Ft., scribed N1/16 S24 BT A 6" Larch, S25°55'W, 17.8 Ft., scribed N 1/16 S23 BT

N 1/16
S23 | S2l<sub>1</sub>
5612S
1979

SKETCH, WITH COURSE AND DISTANCE TO ADJACENT CORNERS IF DETERMINED IN THIS SURVEY. (MAY SKETCH OR PASTE REPRODUCTION ON REVERSE SIDE.)

See Certificate of Survey No. 750

Surveyor's Seal




I, ......certify that the information shown herein is true and correct.

Signature of Ground Party Chief

I, Thomas: C. Hill
certify that I have carefully performed or reviewed the
work done on the diagrammed corner as reported on this
recordation form and approve the same.

Signature of Surveyor

DIAGRAM OF CORNER:



= Corner recorded on the sheet

5612-S Registration Number

Office of Clerk and Recorder, County of Lincoln

This "corner record" was filed for record on the 3nd day of March 1980, was noted

..... 198Q..., was noted on the cross-index plat and is

assigned page No. 619 , in book No.

Eleanor L. Daughar, by Detty Bul, County Official Deputy No. D. 21 T. 34 P. 26 Mar

the second of the second of **(D**