
## **CERTIFIED CORNER RECORDATION**

Corner S 1/16 Sec. 7 & 12 T. 34N R. 26W P.M., MT Lincoln County

- I. No previous history.
- II. Nothing found.
- III. At the position as determined by survey, set a 2 1/2 ins. diam., 30 ins. long alum. pipe, with a 3 1/4 ins. diam. alum. cap, 2 ins. above ground, marked as shown:



## Established two bearing trees:


A spruce, 15 ins. diam., bears S63°W, 27.2 ft. dist., scribed "X" " BT". A spruce, 9 ins. diam., bears S40°E, 21.9 ft. dist., scribed "S 1/16 S7 BT".

Painted bearing trees and attached Land Survey Monument and Bearing Tree signs.

Set a 6 ft. galvanized steel post, North, 3.0 ft. dist., with Land Survey Monument and Property Boundary decals.

Set a 6 ft. galvanized steel post, East, 3.0 ft. dist., with Land Survey Monument and Property Boundary decals.

Magnetic Declination: 20° East.



Cross Index No.

H-01

<sup>T.</sup> 34N

26W P.M., M

