CERTIFIED LAND CORNER RECORDATION

(REFERENCE FSM 7153.53)

DESCRIPTION OF CORNER EVIDENCE FOUND, AND ORIGINAL RECORD (IF KNOWN)

A steel fence post found by compass and chaining.

FOUND A 2/2"ALUMINUM PIPE STAMPED "S6125" AS PER COFS #748 \$ 750 \$ RECORDATION FROM
POSITION FOUND TO BE IN ERROR, SO I PULLED PIPE UP AND SET IN POSITION AS BELOW.
REFER TO THE CORRECTION TO COFS #748 \$ 750

DESCRIPTION OF MONUMENT AND ACCESSORIES ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

Amended S23
At the corner point of the W1/16 S26:

Date of work: 10/22/80

Set a $2\frac{1}{2}$ "x30" alum. pipe appr. 25" in ground with alum. cap marked as shown: Collar of stone.

From which: A 8" pine bears S05°W., 29.2 ft. Marked: "W1/16 S 26 BT."
A 8" larch bears S73°W., 10.9 ft. Marked: "W 1/16 S23 BT."

\(\frac{\W\/16}{523}\)
\(\frac{523}{526}\)
\(\frac{56125}{1980}\)


Attached location poster to a 7" pine which bears S22°E., 7.5 ft. Attached bearing tree signs.

Painted red bands around bearing trees.

Above mentioned appr. fence post bears N52°E., 3.5 ft.

SKETCH, WITH COURSE AND DISTANCE TO ADJACENT CORNERS IF DETERMINED IN THIS SURVEY.

(MAY SKETCH OR PASTE REPRODUCTION ON REVERSE SIDE.)



No Scale

Surveyor's Seal



I, Anthony J. Bachman certify that the information shown herein is true and correct.

Signature of Ground Party Chief

I, Thomas C. Hill
certify that I have carefully performed or reviewed the
work done on the diagrammed corner as reported on this
recordation form and approve the same.

Signature of Surveyor

DIAGRAM OF CORNER:

N. 734N R26W W/16 SEC 23

= Corner recorded on the sheet

5612-S Registration Number

Office of Clerk and Recorder, County of SINCOLO	
	Tebruary 1981, was noted on the cross-index plat and is
assigned page No. 778 in book No	Eleanor d. Vaughn by Michele Groom,
, and page 110.4.4.4.	
•	Cross Index No. R-18 T. 34N R26W Men

o provious possed of same unbablica on fills. THENTHE IT 10000

','`', I

O

and with a gradient