CERTIFIED LAND CORNER RECORDATION

(REFERENCE FSM 7153.53)

DESCRIPTION OF CORNER EVIDENCE FOUND, AND ORIGINAL RECORD (IF KNOWN)

Found a steel fence post by compass and chaining. FOUND A 2/2" BRASS ROCK CAP STAMPED "5612S 1979" AS PER SCOP THE RECORDATION FORM BKI PG 677 POSITION FOUND TO BE IN ERROR, REFER TO CORRECTION TO COS #748 DESCRIPTION OF MONUMENT AND ACCESSORIES ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER: 11/12/80 Date of work:.. AMENDED At the corner position of the CN1/16 S26: Set a brass rock cap in limestone bedrock. Marked as shown: From which: A 7" larch bears SO3°W., 14.4 ft. Marked: "CN1/16 S26 BT." A 7" douglas fir bears S71°E., Marked: "XBT." 526 Attached location poster to a 4" larch which bears S46°W., 6.3 ft. 56125 Attached bearing tree signs. 980 Painted red bands around bearing trees. Above mentioned appr. corner post bears Sou"W., 15.6 ft. SKETCH, WITH COURSE AND DISTANCE TO ADJACENT CORNERS IF DETERMINED IN THIS SURVEY.

(MAY SKETCH OR PASTE REPRODUCTION ON REVERSE SIDE.) No Scale

THOMAS C.
HILL
5612 S

ACOISTERED ONLY

SURVE

Surveyor's Seal

Anthony J. Bachman
certify that the information shown herein is true and correct.

Attom A Backman
Signature of Ground Party Chief

certify that I have carefully performed or reviewed the work done on the diagrammed corner as reported on this recordation form and approve the same.

Signature of Surveyor

5612-S
Registration Number

DIAGRAM OF CORNER:

T34N R26N
CN 116
N. SEC 26

Corner recorded on the sheet

Office of Clerk and Recorder, County of Lincoln	1
This "corner record" was filed for record on the day of Jebruauf 19.81., was noted on the cross-index plat and is	
assigned page No. 980, in book No. /	Eleanor L. Vaughr, by Michel Groom,
	Cross Index No. 5-19 T 34N R 26W Mer.

o previous record of norm intation on files io evidence found on promet. ALUMNUM PINE in maint - <u>'I</u>.'