


# CERTIFIED CORNER RECORDATION

Corner E 1/16 Secs. 12 & 13 T. 34N R. 27W P.M., MT Lincoln County

- I. No previous history.
- II. No evidence found.
- II. Set by survey, a 30 ins. long aluminum pipe, 2 1/2 in. diam., 18 ins. in the ground, with a 3 1/4 in. diam. aluminum cap mkd. as shown.




Established two new bearing trees:

- A larch, 11 ins. diam., bears S25°W, 6.0 ft. dist., mkd. "E 1/16 S12 BT".
- A fir, 16 ins. diam., bears N61°W, 18.5 ft. dist., mkd. "E 1/16 S12 BT".
- A 6 ft. galvanized steel guard post, North, 3.0 ft. dist.

Painted bearing trees and attached Land Survey Monument and Bearing Tree signs.  
Attached Land Survey Monument and Property Boundary decals to the post.

Magnetic Declination: 20° East.



SKETCH OF CORNER

CERTIFICATION	
I, <u>Mark Federman</u>	
certify the information shown herein is true and correct.	
<u>Mark Federman</u>	
I, <u>Alvah F. Hughes</u>	
certify that this Corner Record correctly represents work performed by me or under my direction in compliance with the "Corner Recordation Act", (70-22-101, et seq., M.C.A.)	
<u>Alvah F. Hughes</u>	
Signature of Surveyor & Seal	
Date:	<u>10/23/97</u>
Reg. No.:	<u>7322LS</u>
Employer:	<u>U.S. FOREST SERVICE</u>

Office of Clerk and Recorder, County of Lincoln This "corner record" was filed for record on 12-26-97 was noted on the cross-index plat and is assigned page No. 10020 in book No. \_\_\_\_\_

Carol M. Cummings, L.S.  
County Official

Sec. 13


● - corner this sheet