## **CERTIFIED CORNER RECORDATION**

Corner	HES 1065	Sec.	21	Т.	34N	R.	34W	P.M., MT	Lincoln	County
	Cor. 8									

1921 Homestead Entry No. 1065 by Grant Higgins: To listing cor. No. 8, mkd. and witnessed as I. described by the District Forester. I destroy the listing cor. and its accessories and in its place, establish cor. No. 8 of this survey, as follows: Place a small stone, mkd. with a cross (x) under a sandstone, 24x10x4 ins., 14 ins. in the ground, mkd. "8 HES 1065", on SW face and a cross (x) on top for the exact corner point.

Established two bearing trees:

A cross (x) on a white pine tree, 8 ins. diam., bears \$70°39'E, 16 lks. dist. A cross (x) on a white pine tree, 7 ins. diam., bears \$46°50'W, 21 lks. dist.

Each bearing tree is blazed and scribed "8 HES 1065 BT. Raise a mound of earth and stone, 4.0 ft. base, 2.0 ft. high, SW of the corner.

- Found a 5x12 in. stone, protruding 7 ins. above the ground, firmly set, mkd. "8 HES 1065" on the SW II. face, with an "x" on top. No evidence found of the original bearing trees.
- III. Established two new bearing trees:

A fir, 11 ins. diam., bears N22°E, 51.4 ft. dist., mkd. "8 HES 1065 BT". A pine, 11 ins. diam., bears N75°E, 45.6 ft. dist., mkd. "8 HES 1065 BT".

Painted bearing trees and attached Land Survey Monument and Bearing Tree signs.

Magnetic Declination: 20° East.

