INSTRUCTIONS

- 2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated
- 3. Description of monument and accessories set to perpetuate the corner position.

 4. Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.
- Certification must be signed and sealed by Registered Land Surveyor in State of Montana.
 Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED	CORNER	RECORDATIO	Ν
-----------	--------	------------	---

WE 1/6L County P.M.M. .

Date of work: June 25,18

- I. No previous record of monumentation on file.
- No evidence found on ground.
- At the determined corner point: Set a $2\frac{1}{2}$ "x30" alum. pipe appr. 15" in the ground, collar of stone. Alum. cap mrk. as shown:

From which:

A 4" pine bears S06°E., 12.0 ft. Mrk.: "XBT." A 10" western larch bears N23°W., 29.3 ft. Mrk.: "1/64S33BT."

Attached location poster to a 4" pine which bears NO2°E., 5.7 ft.

Bearings taken to center of tree, distance measured to nail at base of tree.

Painted red bands around Bt's, and attached BT signs.

No SCALE

WEST 1330.26"



10°WL533BT	CERTIFICATION I. Anthony J. Bachman certify the information shown herein is true and correct.
\$33 WE 1/64 \$4 5612.5	Signature Ground Party Chief 1. Thomas C. Hill certify that this Corner Record correctly represents work performed by me or under by direction in compliance with the "Corner Recordation Act" (78-22-101, et seq., M.D.A.) Signature of Surveyor & Seal Date: 7-27-81 Reg. No. 56/2-5 Employer:
Office of Clerk and Recorder, County of Lincoln	Sec. 33

day of 198%, record" was filed for record on the _ was noted on the cross-index plat and is assigned page No. book No. County Official

- corner this sheet