## INSTRUCTIONS.,

1. Original and/or subsequent record used to evaluate the corner position.

- 2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated corners.
- 3. Description of monument and accessories set to perpetuate the corner position.
- 4. Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories.
- 5. Certification must be signed and sealed by Land Surveyor registered in the State of Montana.
- 6. Fill in Cross Index & Section Diagram at bottom of sheet.

## CERTIFIED CORNER RECORDATION

Corner: 3 HES 750, Section 8 T.34N. R. 34W. P.M.M. <u>Lincoln</u> County

Set a small stone, marked with a cross (x) under a quartzite stone, 24 ins. x 7 ins. x 3 ins., 14 ins. in the ground, marked "3HES750" on south face and a cross (x) on top for 1917 GLO Record:

exact corner point, from which:

A Larch, 10 ins. dia., bears  $S7^{\circ}15$  W, 27 lks (17.8 ft.), marked with a cross and scribed "3HES750BT"

A Red fir, 8 ins. dia., bears N51°W, 33 lks (21.8 ft.), marked with a cross and scribed

"3HES750BT"

Raise a mound of earth, 4 ft. base, 2 ft. high, Southwest of corner.

2010 Found:

We find a stone monument, 2-1/2 ins. x 7-1/2 ins., 0.9 ft. above ground, marked

"3HES750" on the south face. No evidence of bearing trees found.

2010 Perpetuation: Establish new bearing trees as follows:

A Douglas fir, 13 ins. dia., bears S35°30'E, 33.2 ft., scribed "3HES750RM2"

A Douglas fir, 14.5 ins. dia., bears N73°30'E, 26.3 ft., scribed "3HES750RM1"

Bearing trees affixed with BT tags, LSM signs, snow blazed and painted red bands.

Steel spikes driven into BT's, side center at point of measurement.

We set a galvanized steel post, N64°30'E, 0.6 ft. from monument, with LSM and USFS

boundary decals.

See back side for corner exhibit CERTIFICATION Keith Brandt certify the information shown herein is true and correct.

Signature Ground Party Chief I, Ken E Jenkins
certify that this Corner Record correctly represents work performed by mo or under my direction in compliance with the "Constant FT" (70-22-101, et seq. 14.5.2.2) Found Stone Signature of Surveyor & Seal Date: 1/2011 Reg. No. 9330 LS Employer: Montana Northwest Company P.O. Box 8777, Missoula, MT 59807 406-721-4033 Project No.1617-10 SKETCH OF CORNER

			Sec. 8		
Office of Clerk and Recorder, County of	This "corner				
231919 BOOK: CCR CCER'S record was filed for record o STATE OF MONTANA LINCOLN COUN	PAGE: 11862 Pages: 2		-		<u> </u>
DECORDED. 03/31/2011 10.35					-
was noted on the cross-index TAMMY D. LAUER CLERK AND REC	ORDER				
book No	BOX 8777, MISSOULA, MONTANA	•			

County Official

