INSTRUCTIONS

1. Original and/or subsequent record used to evaluate the corner position.

2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated corners.

3. Description of monument and accessories set to perpetuate the corner position.

4. Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.

5. Certification must be signed and sealed by Land Surveyor registered in the State of Montana.

6. Fill in Cross Index & Section Diagram at bottom of sheet. *

	RECORD	

Cor	4 of HES 413		TR.	33 W.,	_ P.M.M	Lincoln	County
Ι.	mkd. 4 HES 413 on SE	record by E. R. John face, and a cross on a mound of stone 4 f	top for the exa	ct corner po	int. No be		_
11.	face and a cross on	sandstone, firmly set top. On the NE face, Yaak River. I accept	stone is mkd. 1	HES 1165. Mo	und of sto	ne not found,	possibly due to
111.	A cedar, 15 ins	. dia., bears S77 E, . dia., bears S1 W, 2 ound the bearing tree ed steel guard post w	9.7 ft. dist., m	kd. 4 HES 41 and Survey M	3 BT.		-

	CERTIFICATION I. Ray Pederson certify the information shown herein is true and correct.
15"CEDAR	Signature Ground Party Chief Alvah F. Hughes certify that this Corner Record correctly represents work performed by me or under my direction in coordinate with the "Corner Recordation Act" (70-22-101, et seq. M.C.) Signature of Surveys (4-Seal) Date: 1/8/91 Reg. No. 7322 43
SKETCH OF CORNER	Employer U.S. FOREST SERVICE//
Office of Clerk and Recorder, County of Lincoln record" was filed for record on 1-10-91	Sec. 16
was noted on the cross mack plat and is assigned page 110.	4475 in
book No Cosal M Cumpus County (Official HES

Cross Index No. ..

4 HES 413

34 N

33 W

corner this sheet