INSTRUCTIONS


- Original and/or subsequent record used to evaluate the corner position
- 2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated
- 3. Description of monument and accessories set to perpetuate the corner position.
 4. Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.
- 5. Certification must be signed and sealed by Land Surveyor registered in the State of Montana.
 6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

T. ______R. _____P.M.M. 5 of HES 413 Lincoln Corner . County 1915 H.E.S. original record by E. R. Johnson: Set a sandstone 24 by 12 by 9 ins., 14 ins. in the ground. mkd. 5 HES 413 on SW face, and a cross on top for the exact corner point, from which A cross on a white pine, 20 ins. dia., bears N58 02'E, 63 lks.(41.58 ft) dist. A cross on a cedar, 24 ins. dia., bears N51 52'W, 25 lks.(16.50 ft.) dist. Each blazed and scribed 5 HES 413 BT Raised a mound of earth, 4 ft. base, 2 ft. high, SW of corner. II. Found a 12 by 9 ins. sandstone, firmly set, protruding 8 ins. out of the ground, mkd. 5 HES 413 on SW face and a cross on top. On the NW face, stone is mkd. 7 HES 1165. From which A fallen pine, 24 ins. dia., bears N57 E. 41.4 ft. dist., mkd. 5 HES 413.

A fallen cedar, 25 ins. dia., bears N51 W, 16.2 ft. dist., no visible scribing. III. Established two new bearing trees A larch, 9 ins. dia., bears S77 E, 12.6 ft. dist., mkd. 5 HES 413 BT. A spruce, 8 ins. dia., bears N10 W, 28.6 ft. dist., mkd. 5 HES 413 BT.

Painted red bands around the bearing trees and attached Land Survey Monument and Bearing Tree signs. Set a 6 ft. galvanized steel guard post with Land Survey Marker and Property Boundary decals, S5 W. 3 ft. Magnetic declination: 20 East.



Cross Index No. .

5 HES 413

33 W

PMM

· corner this sheet

book No. __