INSTRUCTIONS

- Original and/or subsequent record used to evaluate the corner position.
 Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated corners.
- 3. Description of monument and accessories set to perpetuate the corner position.

 4. Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.
- 6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

9 of MS 5024 Lincoln Corner_ County 1896 MS original record by Abram L. Jaqueth: "Eight Course, N.58 35'W. Loc. Cor. set a post 6 ins.


square, 6 ft. long, 2 ft. deep, marked 9-5024 for Cor. No. 9. A blazed hemlock tree, 12 ins. in diam., marked BT 9-5024, bears N.7 $^{\circ}$ 00'E., 5 ft. dist.

A blazed tamarack tree, 28 ins. in diam., marked 9-5024 BT, bears S.12 00'W., 24 ft. dist."

II. Found a 2 ft. diam., 1 ft. high mound of stone with a hole and rotten wood in the center.

A larch stump, 28 ins. diam., bears S.16 W., 25.0 ft. dist, burnt face.

III.At determined rotten wood post remains, set a 3/4 ins. diam., 30 ins long aluminum rod, 24 ins. in the ground with aluminum cap mkd. as shown:



Established two new bearing trees:

A larch, 12 ins. diam., bears $8.43^{\circ}E$., 27.4 ft. dist., mkd. 9 MS 5024 BT. A larch, 11 ins. diam., bears $8.66^{\circ}W$., 21.5 ft. dist., mkd. 9 MS 5024 BT.

Painted red bands around the bearing trees and attached "Land Survey Monument" and "Bearing Tree"

Set galvanized a steel guard post with "Land Survey Marker" and "Property Boundary" decals, N.13 E., 3 ft. dist. from corner.

Magnetic declination: 20 East



CERTIFICATION Kevin A. Todd certify the information shown herein is true and correct. 1 och Ronald A. Pearson certify that this Corner Record correctly represents work performed by me or under my direction in com Recordation Act" (70-22-101, et seq., M-4 Signature of Surveyor & Seal 11/26/91 Reg. No. 9008 LS 28" STUMP U.S. FOREST SERVICE SKETCH OF CORNER Employer: Sec. 21

Office of Clerk and Recorder, County of \bot . This "corner an 16,1992 record" was filed for record on was noted on the cross-index plat and is assigned page No. 4652 book No. -9 MS 5024

· - corner this sheet