CERTIFIED CORNER RECORDATION

Corner	HES 845	Sec.	9	T.	34N	R.	33W	P.M., MT	Lincoln	County
	Cor. 5									

1917 Homestead Entry Survey No. 845 by E. R. Johnson: Adopt a granite ledge, 6x5x4 ft., for cor. no. I. 5 of this survey, and mark it "5 HES 845" on the N.W. face and a cross (x) on top for the exact corner point. Established two bearing trees.

1982 Certificate of Survey No. 1053 by M. D. Lauteren, 4232-S: Found a rock outcrop, mkd. with an "x".

1989 Certified Corner Recordation by Alvah F. Hughes, 7322 LS: Found a rock outcrop, 19x7x4 ft., mkd. with an "x" on the top and "5 HES 845" on the N.W. face. Found two bearing trees.

Established one new bearing tree and set one steel guard post:

A larch, 11 ins. diam., bears N87°E, 23.8 ft. dist., mkd. "5 HES 845 BT".

A 6 ft. steel post, bears N81°W, 7 ft. of the corner, with Land Survey Monument and Property Boundary decals attached.

Found a granite ledge, 4 ft. tall, with a road on the top of it, mkd. "5 HES 845" on the N.W. face and II. an "x" on the top.

from which:

A larch, 11 ins. diam., bears N87°E, 23.8 ft. dist., mkd. "5 HES 845 BT". (1982-record)

A white pine snag, bears S02°W, 43.5 ft. dist., with a healed face. (1917-record)
A guard post, bearing N81°W, 7.0 ft. dist. of the corner, with Land Survey Monument and Property Boundary decals attached, surrounded by a pile of stone.


Cleared away road debris on top of markings and painted the ledge with red paint. III.

Established one bearing tree:

A white pine, 12 ins. diam., bears S37°W, 23.9 ft. dist., mkd. "5 HES 845 BT".

Resigned the larch bearing tree, and painted all bearing trees.


Magnetic Declination: 20° East.



. Rex O. Rice Ronald A. Pearson Date: <u>09/17/97</u> Reg. No.: 9008LS Employer: U.S. FOREST SERVICE

mooks This "corner record" was filed for record Office of Clerk and Recorder, County of was noted on the cross-index plat and is assigned page No.

in book No. ___ County Official



- corner this sheet