
CERTIFIED CORNER RECORDATION

Lincoln 27W P.M., MT County 35N 1/4 25&36 Corner Sec.

1913 G.L.O. Original Record by Royston C. Durnford et.al.: Set a slate stone, 14x12x10 ins., 10 ins. in I. the ground, for 1/4 sec. cor., mkd. "1/4" on N. face. Established two bearing trees.

1961 B.L.M. Remonumentation Record by David R. Cunningham et.al.: The 1/4 sec. cor. of secs. 25 & 36, monumented with a slate stone, 14x10x10 ins., loosely set, and mkd. "1/4" on the N. face, and witnessed by the original bearing trees. At the corner point, set an iron post, 30 ins. long, 2 1/2 in. diam., 26 ins. in the ground, in concrete, with a brass cap mkd. as shown.



Established two new bearing trees and buried the original stone alongside the iron post.

Found a B.L.M. brass cap, protruding 2 ins. above the ground, frimly set, mkd. as shown above, II. from which:

A dead fir, 25 ins. diam., bears N09°E, 34.3 ft. dist., with a healed face. (GLO-record)

A larch, 21 ins. diam., bears S07°W, 40.1 ft. dist., with a healed face. (GLO-record) A larch, 14 ins. diam., bears S23°W, 52.3 ft. dist., with a healed face. (BLM-record)

A larch, 10 ins. diam., bears N15°W, 33.3 ft. dist., with a healed face. (BLM-record)

III. Painted bearing trees and attached Land Survey Monument and Bearing Tree signs.

Magnetic Declination: 20° East.

