
-CERTIFIED CORNER RECORDATION

										
Corner	E 1/16	Secs.	28&33	Т.	35N	R.	27W	P.M., MT	Lincoln	County

- I. No previous history.
- II. No evidence found.
- III. Set by survey, a 3/4 in. diam. aluminum rod, 30 ins. long, 27 ins. in the ground, with a 3 1/4 in. diam. aluminum cap, mkd. as shown.




Established two bearing trees:

A larch, 9 ins. diam., bears S52°E, 8.5 ft. dist., mkd. "E 1/16 S33 BT". A spruce, 9 ins. diam., bears S46°W, 31.9 ft. dist., mkd. "E 1/16 S33 BT".

Painted bearing trees and attached Land Survey Monument and Bearing Tree signs.

Magnetic Declination: 20° East



CERTIFICATION

I. Steven A. Boyer

Certify the information shown herein is true and correct.

I. Alvah F. Hughes

Certify that this Corner Record correctly represents work performed by many direction in compliance with the Corner Recordation, Activity 22-101; et.spin (A.)

Signature of Surveyor Assets

Date: 4/22/99

Reg. No.: 7322LS

Employer: U.S. FOREST SERVICE

 Sec. 28

Cross Index No.

V-12

T. 35N

27W

- corner this sh