CERTIFIED CORNER RECORDATION

CS 1/16 Sec. 7 T 35 N. R. 27 W. P.M.M. LINCOLN County

- Record: 1975 Certificate of Survey #104 by J. W. Ninnneman subdivides the SE 1/4 of Section 7 and creates two new parcels in the N 1/2 SW 1/4 SE 1/4 Section 7. Monuments set this survey are "1/2" steel rods, 24" long capped with poly-vinal chloride caps stamped JN 534ES".
- Found a 1/2" rebar with poly-vinal chloride cap marked JHN 534ES.. II.
- The found Ninneman rebar was not accepted as the true position for the CS 1/16 Section III. 7 due to a large positional tolerance discrepancy. At the position determined by survey, set a 5/8 in. diam. X 24 ins. long rebar, flush with the ground with a 3 1/4 in. diam. aluminum cap marked as shown.

T35N R27W S 1/16 | S7 13769LS 2002

From which the new bearing trees:

A fir. 16 ins. diam., N60°W, 37.3 ft., marked CS 1/16 S7 BT. A fir, 9 ins. diam., N27°W, 29.4 ft., marked CS 1/16 S7 BT. JHN rebar bears, N0'59'E, 5.67 ft.


Set a 6 ft. galvanized steel guard post 3.0 ft. north and west, with Property Boundary and Land Survey Monument decals attached. Attached Bearing Tree and Land Survey Monument signs to the bearing trees. Painted red bands around the bearing trees.

Date of Fieldwork: 8/1/2002

Survey crew: Steve Boyer, Tom Hommel Magnetic declination: 20° East assumed


Equipment used: Hand compass and loggers tape

U.S. Forest Service, Supervisiors Office, 1101 Hwy. 2 West, Libby, MT 59923 (406) 293-6211



SKETCH OF CORNER


NOT TO SCALE



Lincoln Office of Clerk and Recorder, County of . This "corner 6an 30, record" was filed for record on _ was noted on the cross-index plat and is assigned page No. (Lummuñ County Official

> _____т. <u>35N.</u>r. <u>27W.</u> р.м., мт Cross Index No. H-03

Adopted July 1, 1981, Montana Board of Professional Engineers & Land Surveyors



corner this sheet