ent record used to evaluate the corner position

Original and/or su
Description of evide

3. Description of monument and accessories set to perpetuate the corner position

Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.

Certification must be signed and sealed by Registered Land Surveyor in State of Montana.

6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

T. 35 N. R. 27 W. P.M.M. Lincoln Corner S E 1/16 Section 10

There is no survey or corner recordation on file for this corner.

There was no evidence of a monumented corner found.

CORNER PERPETUATION

At the corner point: Set a 3/4" x 30" aluminum rod with a 3 1/4" diameter aluminum cap, approx. 26" in the ground, marked:

T35N R27W SE 1/16 S 10 1987

from which bearing trees:

A fir , 9 ins. in dia., bears S 89° W, 51.9 ft. dist., mkd. SE 1/16 S10 BT.

A fir , 10 ins. in dia., bears S 200 W, 21.6 ft. dist., mkd. SE 1/16 S10 BT.

Set a galvanized steel post_with a survey marker_decal and a property boundary decal 2 ft. North of the aluminum cap.

Painted red bands around the bearing trees and painted the scribing. Attached bearing tree signs and attached Survey Monument Signs.

| a" ^ | < #9°₩ | |
|-----------------------------|-----------------------------|---------|
| 9" <u>~</u> Fir <u>~</u> | <u>\$ 89°W</u> \$J.9 Ft. | 10° 66. |

CERTIFICATION certify the information shown herein is true and correct. Signature Ground Party Chief Philip A. Helps certify that this Corner Record correctly represents work performed by me or under by direction in compilance with the Recordation Act" (70-22-10) elseq., M.D.A. KI 4739 S 11/87 Reg. No. Employer: F & H Land Surveying, Whitefish

Declination 20° E. SKETCH OF CORNER

Sec. Office of Clerk and Recorder, County of ____Lincoln Now 30 record" was filed for record on the _ was noted on the cross-index plat and is assigned page Ng. _ book No.