nt record used to evaluate the corner position

1. Original and/or sul 2. Description of evide found, note discrepancies in the record, state method of estab

3. Description of monument and accessories set to perpetuate the corner position

Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking topography ties, position of accessories, etc.

Certification must be signed and sealed by Registered Land Surveyor in State of Montana.

6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

Sec. 3

E. 1/16 Sec. 10

35 N. R. 27 W. P.M.M. Lincoln


RECORD

There is no survey of corner recordation on file for this corner.

There was no evidence of a monumented corner found.

CORNER PERPETUATION

At the corner point: Set a 3/4" x 30" aluminum rod with a 3 1/4" diameter aluminum cap, approx. 26" in the ground, marked:




from which bearing trees:

A fir , 6 ins. in dia., bears N 10° W, 17.4 ft. dist., mkd. E 1/16 S3 BT.

A fir , 8 ins. in dia., bears S 58° E, 15.7 ft. dist., mkd. E 1/16 S10 BT.

Set a galvanized steel post with a survey marker decal and a property boundary decal 3ft. South of the aluminum cap.

Painted red bands around the bearing trees and painted the scribing. Attached bearing tree signs and attached Survey Monument ŝigns.



CERTIFICATION

certify the information shown herein is true and correct.

Signature Ground Party Chief

Philip A. Helps

certify that this Corner Record correctly represents work performed by me or under by direction in compliance with the Recordation Act" (70-22-10), 21/3eq., M.D.A. rq., M.D.A.

4739 S Date: 11/87

Employer: F & H Land Surveying, Whitefish

Declination 20° E. SKETCH OF CORNER

record" was filed for record on the _


book No.

Office of Clerk and Recorder, County of ____Lincoln_

700 30 day of 1987

was noted on the cross-index plat and is assigned page No. _

Cross Index No. E - 16 T. 35 NR 27 W PMM



corner this sheet