INSTRUCTIONS

- 1. Original and/or subsequent record used to evaluate the corner position
- 2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated corners.

3. Description of monument and accessories set to perpetuate the corner position. 4. Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc. 5. Certification must be signed and sealed by Land Surveyor registered in the State of Montana. 6, Fill in Cross Index & Section Diagram at bottom of sheet. **CERTIFIED CORNER RECORDATION** 1 of HES 342 T. ______R. _____P.M.M. 4 of HES 347 Lincoln Corner. County 1915 HES 342 record by Fred E. Thieme: "Set for Cor. No. 1, a shale stone 26x10x7 ins. 1915 HES 347 record by Fred E. Thieme: "To Cor. No. 4, identical with Cor. No. 1 of unapproved HES 342 a shale stone 10x10x7 ins. above ground. 1923 HES 1194 record by J. F. Pfau: "Identical with Cor. No. 4 of accepted HES 347, and Cor. No. 1 of accepted HES No. 342; as this stone is in poor and unstable condition I remove it and in its place reset the cor. and establish Cor. No. 2 of this survey as follows: Place a small stone marked with a cross(x)under a limestone 24x24x4 ins. 14 ins. in the ground, marked 4 HES 347 on NE face, 1 HES 342 on SE face and 2 HES 1194 on W face. No bearings available, therefore dig pits 24x24x12 ins. on this and succeeding course, 7 ft. dist. and raise a mound of earth 4 ft. base, 2 ft. high W of cor. II. Found a stone, 17x4, 7 ins. out of the ground, mkd. 1 HES 342 on SE face, 4 HES 347 on NE face and 2 HES 1194 on SW face. From which An aspen, 14 ins. diam., bears $N44^{\circ}E$, 21.4 ft. dist., mkd. 1 HES 342 BT.(No record) An aspen, 15 ins. diam., bears $N15^{\circ}W$, 30.1 ft. dist., mkd. 1 HES 342 BT.(No record) Above bearing trees were established by JHN in 1977. (According to found BT signs) III. Painted red bands around the bearing trees and attached "Land Survey Monument" and "Bearing Tree" signs. Set a galvanized steel guard post with "Land Survey Marker" and "Property Boundary" decals, N23°w, 3 ft. Magnetic declination: 20° East



corner this sheet

	8UK SUK
15"ASPENA	CERTIFICATION
wit.	Kevin A. Todd
14"ASPEN	certify the information shown herein is true and correct.
The Market of the Control of the Con	Kevin A Todal
NAU F1	Signature Ground Party Chief Ronald A. Pearson
	certify that this Corner Record correctly represents work performe
	by me or under my direction in compliance with the "Corne Recordation Act" (70-22-101, et seq., M.S.A.)
	2 000
	Signature of Surveyor & Seal
•	Date: 12/23/91 Reg. No. 9008 LS
SKETCH OF CORNER	Employer: U.S. FOREST SERVICE
11000/1	Sec. 24
Office of Clerk and Recorder, County of Lincoln	This "corner
record" was filed for record on 16,1992	
was noted on the cross-index plat and is assigned page No.	6/8 in
book No (Oral. CM. Qu	umming HES
My / July market	00 0 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1

Cross Index No.

__ T. _____ R. ___