CENTIFIED CORNER RECORDATION

Corner <u>No. 1 HES 846</u> T. <u>35</u> N., R. <u>33</u> W., P.M.M. <u>Lincoln</u> County

Record:

1917 HES survey by ER Johnson.

"Set a small stone marked with a cross (x) under a quartzite stone 28x9x4 ins., 18 ins. in the ground, marked 1 HES 846 on SE face and a cross (x) on top for exact corner point, from which:

A cross (x) on a larch tree 10 ins. dia. bears N 35°15' E, 47 lks. dist.

A cross (x) on a larch tree 24 ins. dia. bears N 49 $^{\circ}$ 00' W, 23 lks. dist., each blazed and scribed 1 HES 846 BT.

Raise a mound of stone 4 ft. base, 2 ft. high, SE of corner.

1970 PF Plat No. 2532 Pleasant Meadow Subdivision by Sargent, Ramer & Associates Inc. "Set brass capped monument."

1994 Certificate of Survey No. 2158 by Davis Surveying, Inc.

Found Evidence:

The original stone monument and its accessories for Corner No. 1 HES 846 were lost or destroyed during road construction on Hwy. 92 (Yaak Hwy.). A 2 1/2 inch dia. brass cap reported to mark Corner No. 1 per PF Plat No. 2532 was recovered.

Perpetuation:

Corner No. 1 HES 846 was computed using distance distance method from tied corners from HES 846 and using GLO record tie from the established USLM No. 846 found and tied per C. of S. No. 2158, Lincoln County Records, Montana.

At the computed position, set a 5/8 inch dia. alum. rod 30 ins. long, 26 ins. in the ground with a 3 1/4 inch dia. alum. cap marked as shown below, from which:

A 2 inch long PK nail driven flush with the existing hwy. pavement bears S. 84° W., 5.50 ft. dist.

A 2 inch long PK nail driven flush with the existing hwy. pavement bears N. 2° W., 4.87 ft. dist.

The found 2 1/2 inch dia. brass cap per P.F. Plat No. 2532 bears N. 55°41'59" E., 100.81 ft. dist.

Attached Bearing Tree signs on guard rail posts and attached one Land Survey Monument sign to guard rail post.

Set a steel guard post with Property Line and Land Survey Monument decals 2 ft. dist. southwesterly on line.

Magnetic Declination: 18° East

Sketch of Corner	CERTIFICATION I, John Damon certify the information shown hereign is invelled to the control of the certify the information shown hereign is invelled to the certify the information shown hereign is invelled to the certify that this Corner Record prreatily represents work performed by me of under my direction in compliance with the "Corner Recording the Corner Recording to the certify that this Corner Record prreatily represents work performed by me of under my direction in compliance with the "Corner Recording to the certific that the corner represents the corner representation and corner represents the cor
2 . 0	Section

Sketch of Corner	Signature of Surveyor & Seal Date: 1-7-98 Reg. No. 4975-S Employer: Davis Surveying, Inc.
Office of Clerk and Recorder, County of	
Cross Index No. <u>1 HES 846</u> T. <u>35</u> N., R. <u>:</u>	33 W., PMM ● THIS CORNER