- Description of evidence to and, note discrepancies in the record, state method of establishing lost or obliterated corners
- Description of monument and accessories set to perpendiate the corner position.

 Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography lies, position of accessories, etc.
- Certification must be signed and scaled by Registered Land Surveyor in State of Montana.
- Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

Corner No. 3 H.E.S. No. 1059 T. 35 N., R. 33 W., P.M.M. Lincoln County {Unsurveyed Section 19 1} Date of Work: September, 1983

1 • Original Record (June: 1921)

Place a small stone, marked with a cross {x} under a Sandstone, 24 x 9 x 4 ins. 14 ins. in the ground, marked 3 HES 1059 on SE. face and a cross {x} on top for the exact corner point.

> No bearings available, therefore dig pits 24 X 24 X 12 ins. crosswise on line on this and the succeeding course, 7 ft. dist.

> Raise a mound of Stone, 4 ft. base, 2 ft. high, SE. of Corner.

Evidence found {September, 1983}

Found a 9 x 4 ins. stone, approx. L ins. above ground, marked 3 HES 1059 on SE. face and a cross [x] on top for the exact corner point.

> Found evidence of pits on courses going easterly and southerly from the stone monument approx. 7 ft. dist.

Found a mound of Stone SE, of Corner.

Perpetuation {September,1983} Э.

Painted original stone monument marking Corner No. 3 HES No. 1859 red, drive a 3 foot lath alongside with identifying information, from which:

A Larch tree, & ins. dia., bears S. 650 W., 2.3 feet dist.

A Larch tree, 7 ins. dia., bears N. 59° E., 18.3 feet dist.

Each marked with a cross {x} above a blaze scribed: 3 HES 1059 BT, cross and face of blaze of each painted red with a red ring painted around the trees at cross {x}.

r<u>35 r</u>33 pmm

