

INSTRUCTIONS

1. Original and/or subsequent record used to evaluate the corner position.
2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated corners.
3. Description of monument and accessories set to perpetuate the corner position.
4. Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.
5. Certification must be signed and sealed by Registered Land Surveyor in State of Montana.
6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

Corner No. 5 H.E.S. No. 1059 T. 35 N., R. 33 W., P.M.M. Lincoln County
{Unsurveyed Section 19} Date of Work: September, 1983

1. Original Record {June, 1921}

Place a small stone, marked with a cross {x} under a sandstone, 24 x 8 x 8 ins., 14 ins. in the ground, marked 5 HES 1059 on SW. face and a cross {x} on top for the exact corner point, from which:

A cross {x} on a cedar tree, 6 ins. dia., bears N. 33° 14' W., 30 lks. dist.

A cross {x} on a cedar tree, 10 ins. dia., bears S. 22° 29' W., 111 lks. dist.

Each blazed and scribed: 5 HES 1059 BT

Raise a mound of stone, 4 ft. base, 2 ft. high, SW of corner.

2. Evidence found {September, 1983}

No evidence of the Original Stone Monument marking Corner No. 5 of HES No. 1059 could be found at or near the record position. No evidence of the witness trees or mound of stone at or near their reported record positions could be found either. Several trees large enough to have apparently been available for witness trees in 1921 were found closer than the reported 10 ins. dia. cedar S. 22° 29' W., 111 lks. dist. from the record corner position. There is something mysterious about this corner, but we were unable to solve the problems thus far to date, other than to assume the corner and its witnessing evidence were all destroyed or set in a location different from the original record position.

3. Perpetuation {September, 1983}


Set a 5/8 inch dia. x 24 inch long rebar with a yellow PVC plastic cap stamped: MDL 4232S, approx. 20 inches in the ground for the monument marking Corner No. 5 H.E.S. No. 1059, painted it red and drive two 3 foot lath adjacent to corner marked with identifying information, from which:

A cedar tree, 5 ins. dia., bears S. 65° W., 4.3 ft. dist.

A cedar tree, 27 ins. dia., bears S. 80 E., 17.0 ft. dist.

Each marked with a cross {x} above a blaze scribed: 5 HES 1059 BT, cross and face of blaze of each painted red with a red ring painted around the trees at cross {x}.

H.E.S.
No.
1059



CERTIFICATION

1. L.A. Dolezal

certify the information shown herein is true and correct.

L.A. Dolezal
Signature Ground Party Chief

1. Melvin D. Lauteren

certify that this Corner Record correctly represents work performed by me or under my direction in compliance with the "Corner Recordation Act" (70-22307, S.C., M.C.)

Melvin D. Lauteren
Signature of Surveyor & Seal

Date: 9-30-83 Reg. No. 4232S

Employer: Kootenai Engineering, Inc.

Office of Clerk and Recorder, County of LINCOLN. This "corner record" ± Sec. 19-T35 N-R 33 W-PMM
 was filed for record on the 3rd day of OCT 19 83, was noted on the cross-index plat and
 is assigned page No. 2349, in book No. James B. Siegel by Betty L. Conner

County Official

Deputy

Cross Index No. 35 R. 33 PMM

COR. No. 5	HES. No. 1059
APPROX. 19.0	ONLY

• - corner this sheet