

INSTRUCTIONS

1. Original and/or subsequent record used to evaluate the corner position.
2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated corners.
3. Description of monument and accessories set to perpetuate the corner position.
4. Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.
5. Certification must be signed and sealed by Registered Land Surveyor in State of Montana.
6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

Corner No. 1 H.E.S. No. 1059 T. 35 N., R. 33 W., P.M.M. Lincoln County
 {Unsurveyed Section 30²} Date of Work: September, 1983

1. {a} Original Record {June, 1921}

Place a small stone, marked with a cross {x} under a Sandstone, 24 x 8 x 5 ins., 14 ins. in the ground, marked 1 HES 1059 on NW. face and a cross {x} on top for the exact corner point, from which:

A cross {x} on a cedar tree, 5 ins. dia., bears S. 30° 40'E., 22 lks. dist.

A cross {x} on a cedar tree, 20 ins. dia., bears N. 5° 26'E., 193 lks. dist.

Each blazed and scribed: 1 HES 1059 BT.

Raise a mound of earth, 4 ft. base, 2 ft. high, NW. of Cor.

{b} Subsequent Record {August, 1921}

Point for listing Cor. No. 1, identical with Cor. No. 1 of H.E.S. No. 1059, which is a sandstone 10 x 8 x 6 ins. above ground, properly marked and witnessed on June 20, 1921. Adopted this Cor. for Cor. No. 4 of the Survey of H.E.S. No. 1074 and marked it 4 HES 1074 on SW. face, with identical witness trees also scribed: 4 HES 1074 BT and raised mound of earth, 4 ft. base, 2 ft. high, SW. of corner.

2. Evidence found {September, 1983}

Found an 8 x 5 inch stone, approx. 5 ins. above ground, marked 1 HES 1059 on NW. face and 4 HES 1074 on SW. face and a cross {x} on top for the exact corner point, from which:


A scarred cedar tree, 20 ins. dia., bears S. 30° 40'E., 22 lks. dist. with possible evidence of cross {x} blazed/scribed faces, leaning out over Yaak River and undermined

A slight mound of earth NW. of Cor.

3. Perpetuation {September, 1983}

Painted Original Stone Monument marking Corner No. 1 HES No. 1059 red, drove 3 foot lath alongside with identifying information, from which:

A Spruce tree, 22 ins. dia., bears S. 33° W., 15.0 feet dist. marked with a cross {x} and face of blaze painted red with a red ring painted around tree and cross {x}.



SKETCH OF CORNER

CERTIFICATION

I, L.A. Dolezal

certify the information shown herein is true and correct.

L.A. Dolezal
 Signature of Party Chief

I, Melvin D. Lauteren

certify that this Corner Record correctly represents work performed by me or under my direction in compliance with the "Corner Recordation Act" (70-22, 1917, M.C.A.)

Melvin D. Lauteren
 Signature of Surveyor & Seal

Date: 9-30-83

Reg. No. 4232S

Employer: Kootenai Engineering, Inc.

Office of Clerk and Recorder, County of LINCOLN. This "corner record" ± Sec. 30-T35N-R33W-PMM was filed for record on the 31st day of OCT. 19 83, was noted on the cross-index plat and is assigned page No. 2350, in book No. Claret B. Sigal by Betty L. Conner

County Official deputy

Cross Index No. _____

T. 35 N. R. 33 W. P.M.M.

COR. No. <u>1</u>	
H.E.S. No. <u>1059</u>	
(APPROX. ONLY)	
<u>30</u>	

• corner this sheet