CERTIFIED CORNER RECORDATION

Corner North 1/16th Cor 13/18 T. 35N R. 25W P.M.M. Lincoln County

<u> 1980 CLC by Thomas C. Hill:</u>

Found:

A 5/8 ins. Rebar with Plastic Cap marked "2989 ES" as per C of S #473

A Alum Cap on a 2½ ins. x 30 ins. alum. pipe, 25 ins. in the ground with a collar of stone; From which:

A Douglas Fir, 9 ins. in diam. bears N31°W, 21.8 ft. mkd. N1/16 S13 BT;


A Douglas Fir, 9 ins. in diam. bears N89°W, 48.4, mkd. X BT;

Attached a location poster on a 6 ins. Douglas Fir which bears N22°W, 20.4 ft.


2. Found:

- A USDA Aluminum monument, 3¼ ins. diam., cap, 5 ins. out of gound surrounded by a mound of stone, mkd. as shown;
- A Douglas Fir, 13 ins. in diam., bears N31°W, 21.80 ft. dist., healed face; A Douglas Fir, 12 ins. in diam., bears N89°W, 48.40 ft. dist., healed face; A Douglas Fir, 10 ins. in diam., bears N22°W, 20.40 ft. dist., with location tag;

- A Carsonite Post with LSM & Boundary tags, bears North, 8 ft. dist.
- 3. Restacked and painted stones around monument. Repainted blazes and rings on all BTs. Placed BT tags & LSM signs on backs of BTs. Placed steel post with LSM & Boundary tags in place of carsonite post.



MAGNETIC DECLINATION - 16' EAST



CURT HECKROTH 9748 LS Employer: GLAHE &

SKETCH OF CORNER

| Office of Clerk and Recorder, | County of <u>Lincoln</u> . This "corner | | |
|--|---|---------|-------------|
| record" was filed for record c | 229602 BOOK: CCR CCGR'S PAGE: 11587 Pages: 1 | Sec. 18 | |
| | STATE OF MONTANA LINCOLN COUNTY RECORDED: 11/15/2010 11:14 KOI: CC&R'S | | |
| | TAMMY D. LAUER CLERK AND DECORDER FEE: \$0.00 BY: Server Server TO: GLAHE & ASSOC., INC. 5.0. BOX 1863, SANDPOINT, ID. 83660, | | |
| | | | |
| Cross Index No. K-1 T. 35N R. 25W PMM | | | |
| Adopted July 1, 1981, Montana Board of Professional Engineers & Land Surveyors | | | |

corner this sheet

• .

.

1.1