CERTIFIED	CORNER	RECORDATION
CENTIFIED	CORNER	RECURDATION

C¼ of S18 _____ T. <u>35N</u> R. <u>25W</u> P.M.M. <u>Lincoln</u> _County

1980 CLC by Thomas C. Hill 5612S:

Found:

An unrecorded 5/8 ins. diam. rebar with a plastic cap stamped "2989 ES" in the position of the C¼ Sec. 18.

A Steel fence post marking approximate corner position bears NO9°E, 3.2 ft. dist. Set:

An Alum Cap on a $2\frac{1}{2}$ ins. x 30 ins. alum. pipe, 27 ins. in the ground, mkd. as shown; A Douglas Fir, 9 ins. in diam. bears N45°E, 22.3 ft. mkd. X BT;

A Douglas Fir, 9 ins. in diam. bears N55'W, 22.6, mkd. C1/4 S18 BT;

Attached a Location poster to a Douglas Fir, 8 ins. in diam. bears N16°W, 7.5 ft. dist. Painted red bands around bearing trees.

2. Found:


A USDA Aluminum monument, 3% ins. cap, 3 ins. out of the ground, surrounded by a mound of stone mkd. as shown;

A Douglas Fir, 13 ins. in diam., bears N45°E, 22.30 ft. dist., healed face;


A Douglas Fir, 12 ins. in diam., bears N55*W, 22.60 ft. dist., healed face; A Douglas Fir, 11 ins. in diam., bears N16*W, 7.50 ft. dist. with location tag; A Carsonite Post with boundary tag bears NE, 1.50 ft. dist.; A Wood Fence corner, 6 ins. in diam., bears East, 2 ft. dist.

3. Repainted stones around monument;

Repainted blazes and rings on all BTs; placed new BT tags to 2 BTs without; Placed Steel Post with LSM & Boundary tags in front of carsonite post, NE, 2 ft. dist.



MAGNETIC DECLINATION - 16' EAST



•