CERTIFIED	CORNER	RECORDATIO	N
V.F. R. I I F. I F. I <i>I</i> .	L.UALVE R	RELLANDATION	ıv

N 16th S19/S20 T. 35N R. 25W P.M.M. Lincoln County

1980 CLC by Thomas C. Hill 5612S:

Found: No previous record of corner establishment on file. Set:

A Cap on a $2\frac{1}{2}$ ins. x 30 ins. alum. pipe, 24 ins. in the ground, with a collar of stone (mound of stone 2 ft. W of corner) and mkd. as shown;


A Western Larch, 11 ins. in diam. bears S78'W, 44.8 ft. dist. mkd. N 1/16 S19 BT;

A Douglas Fir, 13 ins. in diam. bears S81°E, 18.7 ft. dist., mkd. N 1/16 S20 BT;

Attached a Location poster to a Douglas Fir, 9 ins. in diam. bears S79E, 27.5 ft. dist.


2. Found:

- A USDA Aluminum monument, 3¼ ins. cap, 6 ins. out of ground, surrounded by a mound of stone, mkd. as shown;
- A Douglas Fir, 18 ins. in diam., bears S81°E, 18.70 ft. dist., healed face;
- A Western Larch, 12 ins. in diam., bears \$78°W, 44.80 ft. dist., healed face; A Douglas Fir, 14 ins. in diam., bears \$79°E, 27.50 ft. dist. with a location tag;
- A Steel Post with LSM & Boundary tags, bears East, 2.70 ft. dist.
- 3. Restacked and painted stones around monument; Repainted blazes and rings on all BTs; placed Location tag on Record Tree.



corner this sheet

MAGNETIC DECLINATION - 16' EAST



Carried Carried



