CERTIFIED CORNER RECORDATION

Corner C-W-E-W 1/256 S20 T. 35N R. 25W P.M.M. Lincoln County

1980 CLC by Thomas C. Hill 5612S:

Found: No previous record of corner establishment on file. Set:

A Cap on a 2½ ins. x 30 ins. alum. pipe, 25 ins. in the ground, with a collar of stone and mkd. as shown;

A Douglas Fir, 15 ins. in diam. bears N81°W, 19.2 ft. dist. mkd. X BT;

A Douglas Fir, 8 ins. in diam. bears S11°W, 25.9 ft. dist., mkd. 1/256 S20 BT;

Attached a Location poster to a Douglas Fir, 24 ins. in diam. bears N24°E, 10.4 ft. dist.

2. Found:

A USDA Aluminum Monument, 3¼ ins. in diam., 5 ins. out of ground, surrounded by a mound of stone, mkd. as shown;

A Douglas Fir, dying, 10 ins. in diam., bears S11°W, 25.90 ft. dist., healed face; A Douglas Fir, 16 ins. in diam., bears N81°W, 19.20 ft. dist., healed face;

A Douglas Fir, 27 ins. in diam., bears N24E, 10.40 ft. dist. with a location tag;

A Carsonite Post with LSM & Boundary tags, bears South, 2 ft. dist.


3. Established:

A Douglas Fir, 13 ins. in diam., bears S82°E, 56.20 ft. dist. scribed "C-W-E-W 1/256" S20 BT", placed an aluminum nail in side-center.


Restacked and painted stones around monument;

Repainted blazes and rings on all BTs;

Placed Steel Post with LSM & Boundary tags in front of carsonite post, South, 2 ft. dist.



MAGNETIC DECLINATION - 16° EAST



· · ·

•

and the second