CERTIFIED	CORNER	RECORDATIO	N
OLIVIII II.U	V1/1/1/1/1/	- 1\ 1 \ \ \ \ \ \ \ 1\ 1 \ \	·

Corner C-S-NW- 1/64 S29 T. 35N R. 25W P.M.M. Lincoln County

Original GLO Notes:

This corner was never set.

1982 Michael L. Haiges:

Set:

An Alum. Monument with Cap, 31/4 ins. in diam., 21/2 ins. in diam., 30 ins. long; 24 ins. in the ground with protective ring of stone.

A Larch, 9 ins. in diam., bears S78°E, 57.0 ft. dist., mkd. CSNW 1/64 BT;

A Larch, 8 ins. in diam., bears S07°E, 55.1 ft. dist., mkd. CSNW 1/64 BT.


2. Found:

- A Aluminum Monument with 3¼ ins. cap, 6 ins. out of ground surrounded by a mound of stone, mkd. as shown;
- A Western Larch, 12 ins. in diam., bears S78°E, 57.00 ft. dist., healed face; A Western Larch, 10 ins. in diam., bears S7°E, 55.10 ft. dist., healed face;
- A Carsonite post with boundary tag, bears East, 7 ft. dist.
- 3. Restacked and painted stones around monument; Painted blazes and rings on all BTs; placed LSM & Boundary signs on back of BTs; Placed Steel Post with LSM & Boundary tags in front of carsonite post, East, 7 ft. dist.



CERTIFICATION

MAGNETIC DECLINATION - 16° EAST



Adopted July 1, 1981, Montana Board of Professional Engineers & Land Surveyors

corner this sheet