	\triangle	RECORDATION
U.FRIFIFI)	LURINER	RELURIJATION

CS 1/16 S29 _____ T. ___<u>35N</u> R. ___<u>25W</u> P.M.M. <u>Lincoln</u> County

Original GLO Notes:

This corner was never set.

1<u>982 Michael L. Haiges:</u>

Found:


A Brass Cap Monument, 2 ins. in diam., as indicated on Certificate of Survey No. 651/2, records of Lincoln County, Mt.

A Larch, 6 ins. in diam., bears N21°E, 38.0 ft. dist., mkd. CS 1/16 S29 BT;


A Fir, 6 ins. in diam., bears S57°E, 35.9 ft. dist., mkd. CS 1/16 S29 BT.

2. Found:

- A Brass monument, 2½ ins. in diam., 6 ins. out of ground;
- A Western Larch, 8 ins. in diam., bears N21°E, 38.00 ft. dist. with healed face; A Douglas Fir, 16 ins. in diam., bears S57°E, 35.90 ft. dist., with healed face;
- Stacked and painted a mound of stones around monument;
 Repainted blazes and rings on all BTs; placed LSM & Boundary signs on back of BTs;
 Placed Steel Post with LSM & Boundary tags, East, 2 ft. dist.




MAGNETIC DECLINATION - 16' EAST



Office of Clerk and Recorder, County of <u>Lincoln</u> .. This "corner record" was filed for record

STATE OF MONTANA LINCOLN COUNTY PAGE: 11604 Pages: 1 was noted on the cross-in RECORDED: 11/15/2010 11:30 KOI: CCER'S TAMMY D. LAUER CLERK AND RECORDER . book No. . BY; Seanne FEE: \$0.00 TO: GLAHE & ASSOC., INC. N.O. BOX 1863, SANDPOINT, ID. 83860 Cross Index No. U-7 <u>t 35N r 25W pmm</u> Adopted July 1, 1981, Montana Board of Professional Engineers & Land Surveyors



corner this sheet

· · · · ·