CERTIFIED LAND CORNER RECORDATION (REFERENCE FSM 7153.53)

DESCRIPTION OF CORNER EVIDENCE FOUND, AND ORIGINAL RECORD (IF KNOWN)

FOUND A 3/8" REBAR WITH PLASTIC CAP MARKED "2989 ES" AS PER COFS #473.

> DESCRIPTION OF MONUMENT AND ACCESSORIES ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

AT THE CORNER POINT, OVER THE FOUND REBAR: SET A 2 1/2 " X 30" ALUMINUM PIPE APPROX 25" IN GROUND WITH ALUM CAP MARKED AS SHOWN, COLLAR OF STONE. FROM WHICH: A 9" DOUGLAS FIR BEARS N 31°W, 21.8 FT, MEXD "N/16 S13BT" A 9" DOUGLAS FIR BEARS N 89°W, 48.4 FT, MRKD "X BT" ATTACHED LOCATION POSTER ON A 6"DOUGLAS FIR WHICH BEARS N 22°W, 20.4 FT. PAINTED RED BANDS ON BT'S



SKETCH, WITH COURSE AND DISTANCE TO ADJACENT CORNERS IF DETERMINED IN THIS SURVEY. (MAY SKETCH OR PASTE REPRODUCTION ON REVERSE SIDE.)

ONTA IOMAS C HILL 5612 S SURVEY

Surveyor's Seal

_

DIAGRAM OF CORNER: = Corner recorded on the sheet

Signature of Surveyor

uncela) Office of Clerk and Recorder, County of..... This "corner record" was filed for record on the 15th day of December 1960, assigned page No. 943 in book No.

5612S Registration Number

and the second of the second o

Company of the State of the Sta