(REFERENCE FSM 7153.53)

DESCRIPTION OF CORNER EVIDENCE FOUND, AND ORIGINAL RECORD (IF KNOWN)

Found a 21 B.L.M. brass cap approx. 2" above ground marked as shown. Mound of stone approx. 1.5 ft. west of corner.

From which: A 10" fir bears: S58°E, 17.7ft., healed face, alive and in good condition.

> A 7" fir bears N64 E, 28.9 ft., healed face, alive and in good condition.

An 11" fir bears N30°W, 32.6 ft., healled face, alive and in good condition.

A 12" Larch bears S43 W, 38.3 ft., healed face, alive and in good condition.

35NR25 h 517 518 520 1960 BLM


DESCRIPTION OF MONUMENT AND ACCESSORIES ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

Date of work: 6/16/80

Painted red bands around Bearing Trees.

SKETCH, WITH COURSE AND DISTANCE TO ADJACENT CORNERS IF DETERMINED IN THIS SURVEY.

(MAY SKETCH OR PASTE REPRODUCTION ON REVERSE SIDE.)



Surveyor's Seal



I, Anthony J. Bachman certify that the information shown herein is true and correct.

Anthony J. Bachman Signature of Ground Party Chief

Thomas: C. Hill certify that I have carefully performed or reviewed the work done on the diagrammed corner as reported on this recordation form and approve the same

Signature of Surveyor

DIAGRAM OF CORNER:

N. T35N R25W Sec 18 SEC 17 SEC 20 SEC 19

Corner recorded on the sheet

5612-S Registration Number

Lincola Office of Clerk and Recorder, County of.....

This "corner record" was filed for record on the Bull day of Allember ... 19.00., was noted on the cross-index plat and is

County Off

assigned page No. 946, in book No.

Cross Index No. N - 5 T 35N

RQSW

. Mer.

e sum of the 2.2 🔒 😶 .