(REFERENCE FSM 7153.53)

## DESCRIPTION OF CORNER EVIDENCE FOUND, AND ORIGINAL RECORD (IF KNOWN)

Found an unrecorded 5/8" rebar in the position of N E 1/16 S19. Plastic cap marked: 2989ES.

## DESCRIPTION OF MONUMENT AND ACCESSORIES ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

Date of work: 6/4/80


Set a  $2\frac{1}{2}$ " X 30" alum. pipe 25" in the ground with a collar of stone, cap marked as shown:

A 7" douglas fir bears N 53°W, 29.5 FT. marked NE 1/16 S 19 BT. A 10" douglas fir bears N 78°E, 26.7 FT marked: x BT. Attached location poster to a 9" western larch bears N 34°W, 17.3 FT.

\* PLACE FOUND REBAR INSIDE OF PIPE

NE1/16519 5612S 1980

SKETCH, WITH COURSE AND DISTANCE TO ADJACENT CORNERS IF DETERMINED IN THIS SURVEY. (MAY SKETCH OR PASTE REPRODUCTION ON REVERSE SIDE.)



Surveyor's Seal



I, Anthony J. Bachman certify that the information shown herein is true and correct.

of Ground Party Chief Signature


Thomas C. Hill

certify that I have carefully performed or reviewed the work done on the diagrammed corner as reported on this recordation form and approve the same.

Signature of Surveyor

DIAGRAM OF CORNER:

T35N R25W NE 1/16 SEC 19



= Corner recorded on the sheet

5612**-**S Registration Number

Office of Clerk and Recorder, County of..... This "corner record" was filed for record on the 5th day of Alcember ... 1920... as noted on the cross-index plat and assigned page No. 962, in book No. County Official Cross Index No. 0-4 T.35N R.25W Mer.

