
CERTIFIED CORNER RECORDATION

Corner 1/4 Sec. 33&34 T. 35N R. 26W P.M., MT Lincoln County

I. 1894 G.L.O. Original Record by Frank L. Sizer et. al.: Set a wooden post, 3 ft. long 3 ins. square, 24 ins. in the ground, for 1/4 sec. cor., mkd. "1/4 S" on W. face. Established two bearing trees.

1960 Remonumentation Record by David R. Cunningham et. al.: The 1/4 sec. cor. of secs. 33 and 34, as determined from the remains of the two original bearing trees. At the corner point, set an iron post, 30 ins. long, 2 1/2 in. diam., 25 ins. in the ground, in concrete, with brass cap mkd. as shown.



Established two new bearing trees and raise a mound of stone, 3.5 ft. base, 2.5 ft. high, West of the iron post.

II. Found a B.L.M. brass cap, protruding 2 ins. above the ground, firmly set, mkd. as shown above. A mound of stone of stone, 3 ft., West of the monument.

from which:

A rotten stump, bears S46°E, 8.6 ft. dist., with visible scribe. (GLO-record)


A fir, 9 ins. diam., bears S48°E, 24.2 ft. dist., with a healed face. (BLM-record-36 lks., 23.76 ft)

A rotten stump, bears S53°E, 29.55 ft. dist., with visible scribe. (GLO-record-46 lks., 30.36 ft.)

A fir, 13 ins. diam., bears S22°W, 15.2 ft. dist., with a healed face. (BLM-record)

III. Painted bearing trees and attached Land Survey Monument and Bearing Tree signs.

Magnetic Declination: 20° East.



Office of Clerk and Recorder, County of Accol. This "corner record" was filed for record on 12-26-97 was noted on the cross-index plat and is assigned page No. ______ in book No. ______ County Official ______ Corner this sheet

